

**COMMUNITY DEVELOPMENT BLOCK GRANT  
DISASTER RECOVERY PROGRAM  
OWNER OCCUPIED REHABILITATION AND REBUILDING  
CONNECTICUT DEPARTMENT OF HOUSING  
HARTFORD, CONNECTICUT 06118**

RATIO

REAR  
ENTRY ON  
FIRST FLOOR

— APPROXIMATE LOCATION  
OF CHIMNEY

DRIVEWAY



|                 |  |  |
|-----------------|--|--|
| BASEMENT ACCESS |  |  |
|-----------------|--|--|

DOWN

FRONT  
ENTRY ON  
FIRST FLOOR

## BASEMENT & FIRST FLOOR

SCALE 1" = 2'



## 1

WATER DAMAGED INTERIOR WALL AND CEILING BOARD,  
REPLACEMENT AND REPAIR WORK ACCORDING TO  
CONTRACT DOCUMENTS





SCALE 1" = 2'



BRIDGEPORT, CONNECTICUT 06606

|               |                 |                |                  |
|---------------|-----------------|----------------|------------------|
| DRAWN BY: DCK | CHECKED BY: MBR | SCALE: 1" = 2' | DATE: 06/27/2014 |
|---------------|-----------------|----------------|------------------|

CHIMNEY FLASHING REPLACEMENT, ALL WORK ACCORDING  
TO CONTRACT DOCUMENTS

GUTTER AND DOWNSPOUT REPAIR, ALL WORK ACCORDING  
TO CONTRACT DOCUMENTS

BASEMENT BULKHEAD DOOR REPLACEMENT, ALL WORK  
ACCORDING TO CONTRACT DOCUMENTS



ROOF SLOPE ON REAR OF HOUSE)  
(N.T.S.)



(GUTTER)  
(N.T.S.)



(CHIMNEY)  
(N.T.S.)

## ROOF LAYOUT

|             |                            |       |
|-------------|----------------------------|-------|
| JOB NO.     | DRAWING NUMBER             | SHEET |
| 33-262-2240 | BASEMAP<br>33-262-2240.dwg | A-2.0 |